

**Date:** June 2018

**Subject:** Knorr Disc Brake Mounting Bolt on Iveco Drive Axles

**Models:** RT-40-145 / RT46-160 / MC-11-165 / MC-12-175 / MT-23-155

**Dear Customer,**

To align with Iveco assembly practice, the washer beneath the head of the mounting bolt for the Knorr disc brake caliper to torque plate, is being eliminated. This applies to Meritor® axles assembled with Knorr disc brakes in Australia and is in conjunction with a change to a self-locking bolt design and change in bolt length from 50.0mm to 45.0mm. This does not apply to Meritor® axles assembled with Meritor® EX225H disc brakes.

This change was implemented in Meritor® production in June 2018.

Part number summary and description is shown below in table 1.



Existing Part Number	Description	New Part Number	Description
41X5A MWA520P	Bolt, M20 x 50 Washer	16921035 No washer	Bolt, M20 x 45*
 <p>● Washer</p>		<p>* - self-locking bolt for demanding applications</p>  <p>● No Washer</p>	

Table 1: Part Number Summary and Description

### **Servicing and Aftermarket Support**

Care should be taken when servicing the Knorr disc brake assemblies to ensure that the correct bolt design, length and washer combination is used.

For ongoing aftermarket requirements, part number 41X5A has been superseded by 16921035.

For any questions relating to the above, please contact a Meritor® Australia representative on +613-9300-5200.

**Issued by Product Engineering  
Meritor HVSA Ltd**