

Product Information Letter

Meritor Heavy Vehicle Systems
Australia Ltd.
A.B.N. 86 004 479 430
70 Berkshire Road (P.O. Box 25)
Sunshine, Victoria, 3020
Tel: (61 3)9311-6555
Fax: (61 3)9312-1810
Aftermarket Service Parts
Tel: (61 3)9312-4322
Fax: (61 3)9310-2911



PRODUCT INFORMATION LETTER # 04-001

Date: January 2004

Subject: Supersession of Aluminium Drive Axle Hub

Models: 'R' Series Wheel End

Dear Customer

Please be advised of a part number change for the 285mm p.c.d. 10 stud aluminium hub, and hub and drum assemblies to suit 16.5" x 7" brakes, supplied on locally assembled drive axles. This change is brought about by a part number change from the hub supplier.

ArvinMeritor part numbers involved are;

Current Hub and Drum Assembly Number	New Hub and Drum Assembly Number	Description
A1-333-W-101A	A1-333-P-146A	Hub and stud assy.
A4-333-W-101A	A4-333-P-146A	Hub and drum assy. (steel drum).
A5-333-W-101A	A5-333-P-146A	Hub and drum assy. (Centrifuse drum).
A1-333-X-102A	A1-333-Q-147A	Hub and stud assy., machined for ABS pole ring.
A5-333-X-102A	A5-333-Q-147A	Hub and drum assy. (Centrifuse drum), machined for ABS pole ring.
A6-333-X-102A	A6-333-Q-147A	Hub and drum assy. (Centrifuse drum), including ABS pole ring
A7-333-X-102A	A7-333-Q-147A	Hub and drum assy. (steel drum), machined for ABS pole ring.
A8-333-X-102A	A8-333-Q-147A	Hub and drum assy. (steel drum), including ABS pole ring

Use only genuine Meritor parts

An ArvinMeritor brand

Product Information Letter

This change will be implemented as a running change beginning in December 2003, and top level specifications are not affected.

If you have any questions, please contact an ArvinMeritor representative

Issued by Product Engineering
Meritor HVS Australia

Use only genuine Meritor parts
An ArvinMeritor brand