



Date: June 2018
Subject: Steer Axle Camber Change
Models: MFS73

Dear Customer,

As a continuous improvement initiative, Meritor Australia has introduced MFS73 steer axle beams with king pin angles in line with Kenworth recommended values. Specification numbers and steer axle assembly part numbers will not change. Application guidelines and part ratings will remain unchanged.

Customer number	KW01X22A21 or KW01X22A22		KW01X22A31 or KW01X22A32	
	Current	Replaced by	Current	Replaced by
Beam part number	3100Z 78A	3100Z8762	3100Q 95A	3100A8763
King pin angles	6.30L 5.15R	6.30L 5.00R	6.30L 5.15R	6.30L 5.00R
Spring mounting centre	825.5mm (32.5")		864.0mm (34.0")	
Introduction Date	6 th June 2018		27 th June 2018	
Parts leaving Meritor				

The new part numbers are fully interchangeable to those they're replacing and will be introduced into aftermarket as stock is run out.

For any questions relating to the above, please contact a Meritor® Australia representative on +61 3 9300-5200.

**Issued by Product Engineering
Meritor HVSA Ltd**