


Date: 25/06/2019
Subject: New center bearing rubber cushion (50 Durometer Rubber)
Models: RPL 25 Series Centre Bearing Drivelines

Dear Customer,

Meritor Australia would like to inform you of a change in the center bearing rubber cushion used in the RPL 25 Series Centre bearing drivelines. This change will reduce the risk of vibration resonance for chassis-driveline interaction in Kenworth trucks fitted with the RPL 25 drivelines.

This change will be effective on drivelines built from the 25th of June.



The driveline series number will change from 25RHC020B to 25RHC076B with the change in centre bearing.

AFTERMARKET

In the aftermarket catalogue we still offer the HCB206 (Solid Cushion).

Both cushions (HCB214 & HCB206) will be available through normal aftermarket channels.

Centre bearing rubber cushion options will be:

- HCB205: Aftermarket Part Number CB210661-1XSA
- HCB206: Aftermarket Part Number CB210875-1XSA
- HCB214: Aftermarket Part Number HCB214

For any questions relating to the above, please contact a Meritor® Australia representative on + 613 9300 5200.

Issued by Product Engineering
Meritor HVSA Ltd